

CUSTOMER

[REDACTED]
[REDACTED]
[REDACTED] 95@gmail
[REDACTED]

VEHICLE

Fuel	Petrol
Transmission	Automatic
Color	White
Odometer	60 km

INSPECTION

Inspector [REDACTED]
Date [REDACTED]

OVERALL CONDITION

Excellent

INSPECTOR REMARKS

Thank you for choosing CheckMate PDI. Exxpert

A comprehensive Pre-Delivery Inspection (PDI) of the vehicle has been successfully completed. As this is a brand-new vehicle, no road test or test drive was performed to avoid adding unnecessary kilometres before delivery.

The inspection included a thorough examination of the exterior, interior, engine compartment, fluid levels, electrical systems, lights, air conditioning, tyres, wheels, battery, underbody (where accessible), paint finish, body panels, fit & finish, accessories, and all visible components.

The vehicle was found to be in excellent overall condition, with no major defects, damages, warning lights, fluid leaks, or quality concerns observed during the inspection. All inspected components were found to be functioning properly and met the expected delivery standards.

Observation:

- The engine fibre cover retaining lock/clip was found to be broken. This is a minor fitment issue and does not affect the vehicle's engine performance or drivability. However, it is recommended that the dealer replace the damaged retaining lock/clip before vehicle delivery to ensure the engine cover is properly secured.

Final Recommendation:

Based on our inspection findings, the vehicle is recommended for delivery and purchase, subject to the replacement of the damaged engine fibre cover retaining lock/clip. No other significant issues were identified during the inspection.

Thank you for choosing CheckMate PDI. We wish you a smooth delivery experience and many years of safe, happy, and trouble-free motoring.

EXTERIOR





INTERIOR





ENGINE BAY





ODOMETER





VIN PLATE



All Side view

OK

Front Grill

OK



Bonnet

OK



Front Bumper

OK



Left Headlight

OK



Right Headlight

OK



DRL Lights

OK



Fog Lamps

OK



Front Parking Sensors

OK



Left Fender

OK



Left Mirror

OK

Left Front Door

OK



Left Rear Door

OK



Left Quater panel

OK



Left Running board

OK



Right Fender

OK



Right Mirror

OK



Right Front Door

OK

Right Rear Door

OK



Right Quater panel

OK



Right Running board

OK



Rear Bumper

OK



Boot Lid

OK



Top

OK



Roof Rails

OK

Rear Camera

OK

Rear Parking Sensors

OK


Tail Lights

OK



Sunroof

OK



All Side Under Body

OK



Front Windshield

OK



Rear Windshield

OK



Left Glass

OK

Right Glass

OK

Front Left Tyre

OK



Front Right Tyre

OK

Rear Left Tyre

OK

Rear Right Tyre

OK

Spare Wheel

OK



Tyre MFG Date

50 week 2025 year Tyre

Seat Condition

OK

Seats Ventilated

OK



Seat Electrical

OK

Seat Belts

OK

Dashboard Condition

OK

Steering Wheel

OK

Steering Controls

OK



Cruise Control

OK

Infotainment System

OK




Speakers

OK

Reverse Camera

OK



All Parking Sensors

OK

AC Cooling

OK

Ac Vents

OK

Ac Flap Motor

OK

Ac Blower

OK

Cabin Lights

OK

Power Windows

OK



Central Locking

OK

ADAS


OK

Wipers

OK

Car Interior condition

OK



Boot Space

OK



Gearbox condition

OK

Clutch condition

OK

Brake condition

OK

Any Ecm Malfunction

OK

Excel condition

OK

Suspension condition

OK

Engine Oil Level

OK



Engine sludge mark

OK

Engine Wiring

OK

Engine Noise

OK

Engine Tappet cover

OK

Engine head gasket

OK

Engine belt

OK

Engine Tensioner

OK

Coolant Level

OK

Brake Fluid

OK

Battery Condition

OK

Radiator / Fan

OK

Headlights

OK



Indicators

OK

Fog Lamps

OK

Brake Lights

OK



Reverse Lights

OK

Hazard Lights

OK

Horn

OK

TERMS & CONDITIONS

1. Inspection is based on the vehicle's condition at the time of inspection only.
2. This report is not a warranty or guarantee.
3. Hidden or non-visible defects may not be detected.
4. No dismantling or destructive testing is performed.
5. Road test (if conducted) is limited.
6. Future performance of mechanical, electrical, electronic, AC, battery, tyres, paint, and OBD systems is not guaranteed.
7. Vehicle history, accident records, finance, ownership, insurance, and legal documents are not verified unless requested.
8. Odometer accuracy and mileage (KM) tampering cannot be guaranteed.
9. Repairs, modifications, or damage after inspection are outside CheckMate PDI's responsibility.
10. The purchase decision is solely the customer's responsibility.
11. Inspection fees are non-refundable after report delivery.
12. CheckMate PDI's maximum liability is limited to the inspection fee paid.
13. This report is valid only for the inspected vehicle.
14. Third-party use or reliance on this report is prohibited.
15. Acceptance of this report confirms agreement with these Terms & Conditions.

